

LIST OF WORKS FOR MAINTAINANCE OF NON RESIDENTIAL  
BUILDING DURING 2010-11 UNDER DEMAND NO.20-2059 (PUBLIC  
WORKS)

Sl. No.	Name of Work	Provision during 2010-11
1	2	4
	<b>CCE,Potteru Irrigation Project</b>	
	Improvement of Kalimela IB at Kalimela	4.00
	Renovation of P.I. Sub-Division No.IV at MV 64	3.00
	Compound wall at Central Store at Balimela	5.00
	<b>Total ( Potteru)</b>	<b>12.00</b>
	<b>EIC,WR</b>	
	<b>Deputy Director, C&amp;QCS &amp; DS (MP) Division, BBSR</b>	
	Furnishing of room no. 301,302, 306, 331 and 333 of 2nd floor of Secha Sadan	11.00
	<b>Total ( C&amp;QCS&amp;DS)</b>	<b>11.00</b>
	<b>Total ( EIC,WR)</b>	<b>11.00</b>
	<b>CE&amp;BM,LMB</b>	
	<b>Balasore Irrigation Division</b>	
	Repair to Non-residential building inside irrigation colony at Balasore.	4.00
	Improvement to compound wall of Basudevpur Irrigation Sub-Division, Basudevpur.	3.00
	Repair of Jamkunda Irrigation Section at Jamkunda.	3.00
	<b>Sub-Total</b>	<b>10.00</b>
	<b>Jajpur Irrigation Division</b>	
	Improvement & renovation of Jajpur Irrigation Division office, Jajpur.	3.00
	Improvement & renovation of Binjharpur Irrigation Division office	3.00
	Improvement & renovation of Akhuapada Irrigation Sub-Division Office	3.00
	Improvement & renovation of Dhamanagar Irrigation Sub-Division office, Dhamanagar	5.00
	Improvement & renovation of Dasarathpur Irrigation Section Office, Dasarathpur.	2.00
	<b>Sub-Total</b>	<b>16.00</b>
	<b>Jaraka Irrigation Division</b>	
	Renovation of Byree IB	3.00
	Renovation of Jokadia rest shed.	5.00
	Renovation of Barabati IB.	4.00
	Renovation of Chandikhhol Sub-Division.	4.00
	<b>Sub-Total</b>	<b>16.00</b>
	<b>Kendrapara Irrigation Division</b>	
	Repair & restoration to Division Office Building at Kendrapara.	5.00
	Repair to Bantala Section Office.	3.00
	Repair to Section Office at Chaudakulat.	2.00

Sl. No.	Name of Work	Provision during 2010-11
1	2	4
	Repair to Section office & restshed at Gogua.	2.00
	Repair to rest shed at Kakat	1.00
	Repair to Section Office at Chandol.	3.00
	Repair to Section Office at Madhapur.	2.00
	<b>Sub-Total</b>	<b>18.00</b>
	<b>Khurda Irrigation Division</b>	
	Renovation & extension to the existing rest shed at Nayagarh Irrigation Colony, Nayagarh.	8.00
	Repair and restoration to Kuanria Irrigation Sub-Division and Section office at Dasapalla.	8.00
	<b>Sub-Total</b>	<b>16.00</b>
	<b>Mahanadi South Division</b>	
	Improvement to rest shed at Jobra.	5.00
	Improvement to Division office building at Jobra.	10.00
	<b>Sub-Total</b>	<b>15.00</b>
	<b>Mahanadi North Division</b>	
	Improvement to Division office building at Jagatpur.	5.00
	Improvement to I.B at Jagatpur.	4.00
	Improvement to Sub-Division office building at Pundalo.	3.00
	Improvement to restshed at Section office at Nurtanga.	3.00
	Improvement to Sub-Division office at Kendupatna.	3.00
	<b>Sub-Total</b>	<b>18.00</b>
	<b>Nimapara Irrigation Division</b>	
	Improvement to the Sub-Divisional office at Gop.	8.00
	Improvement to the Section office at Bentapur.	5.00
	Improvement to the Section office at Madaranga.	4.00
	<b>Sub-Total</b>	<b>17.00</b>
	<b>Aul Embankment Division</b>	
	Renovation of Talchua Section office at Talchua	4.00
	Repair of Sub division office at Kanika	4.00
	Renovation to Sub-Division office at Rajnagar	10.00
	Improvement to Rest shed of Division office at Aul	1.00
	<b>Sub-Total</b>	<b>19.00</b>
	<b>Puri Irrigation Division</b>	
	Improvement to Puri Irrigation Division Office Building , Puri	4.50
	Improvement to I.B. at Puri	4.00
	Improvement to I.B. at Brahmagiri	2.00
	Improvement to I.B. at Satapada	2.00
	Improvement to I.B. at Torania	2.00
	Improvement to I.B. at Rahadamal	2.00
	Improvement to Sub-Division Office Building at Sakhigopal	2.00
	Improvement to Section Office at Rupadeipur	2.00
	<b>Sub-Total</b>	<b>20.50</b>

Sl. No.	Name of Work	Provision during 2010-11
1	2	4
	<b>Prachi Division</b>	
	Repair and renovation to Section office at Banamalipur.	3.00
	Repair and renovation to Section office at Balianta Andhilo colony.	4.00
	Repair and renovation to Section office at Pahanga.	3.00
	Repair and renovation to Section office at Mahidharpada.	3.00
	Repair and renovation to Section office at Badabil.	3.00
	<b>Sub-Total</b>	<b>16.00</b>
	<b>Jagatsinghpur Irrigation Division</b>	
	Improvement to I.B. at Balikuda.	4.00
	Improvement to I.B. and Section office at Balia.	4.00
	Renovation to A.E. office at Alipingal.	4.00
	Renovation to I.B. at Machhagaon.	4.00
	<b>Sub-Total</b>	<b>16.00</b>
	<b>Total LMB</b>	<b>197.50</b>
	<b>CE&amp;BM Brahmani Right Basin</b>	
	<b>Angul Irrigation Division</b>	
	Improvement to Angul Irrigation Division, Angul	5.00
	Improvement to Flood Section Office, Anlaberini	2.00
	Improvement to Section Office, Dhenkanal	2.00
	Improvement to Sapua Dam sub-division office	3.00
	<b>Total (BRB Basin)</b>	<b>12.00</b>
	<b>CE&amp;BM RVN Basin</b>	
	<b>Kalahandi Irrigation Division</b>	
	Renovation of Office Building of Kalahandi Irrigation Division, Bhawanipatna	8.0
	Restoration of Office Building of Indra Irrigation Sub-Division No. I Khariar	2.0
	Improvement to two nos Annexure suits at Irrigation Rest Shed, Bhawanipatna	2.0
	<b>Sub-Total</b>	<b>12.00</b>
	<b>Bhanjanagar Irrigation Division</b>	
	Improvement to Division Office of Bhanjanagar Irrigation Division	10.00
	Improvement to Sub-Division office of Bhanjanagar Sub-Division	10.00
	<b>Sub-Total</b>	<b>20.00</b>
	<b>Berhampur Irrigation Division</b>	
	Improvement to Karuna Ib	5.00
	Improvement to Asst. Executive Engineer, Office Building	3.00
	Improvement to Narendrapur Section Office Building	2.00
	Improvement to Office Building of EE, Berhampur Irrigation Division, Berhampur	5.00
	Improvement to Assistant Engineer, Dhanei Irrigation Sub-Division Office Building at Chirikipadasasan	2.00
	Improvement to Dhanei Ib	3.00
	<b>Sub-Total</b>	<b>20.00</b>
	<b>Boudh Irrigation Division</b>	
	Improvement to I.B. at Boudh	7.50
	Improvement to Division Office Building	7.50
	<b>Sub-Total</b>	<b>15.00</b>

Sl. No.	Name of Work	Provision during 2010-11
1	2	4
	<b>Chikiti Irrigation Division</b>	
	Improvement to Office rooms of Southern Irrigation Circle	5.00
	Improvement to Ghodahada Irrigation Sub-Division Office Building	2.00
	Improvement to Sub-Division office building at Paralakhemundi	5.00
	Improvement to Rest Shed at Ghodahada of Ghodahada Project	2.00
	<b>Sub-Total</b>	<b>14.00</b>
	<b>Harbhangi Irrigation Division</b>	
	Improvement to Division Office building at Adava	10.00
	<b>Sub-Total</b>	<b>10.00</b>
	<b>Nuapada Irrigation Division</b>	
	Improvement to IB at Nuapada	4.00
	Improvement to Divn. Office	4.00
	Improvement to Sub division office, Komna	2.00
	<b>Sub-Total</b>	<b>10.00</b>
	<b>Total CE&amp;BM,RVN</b>	<b>101.00</b>
	<b>Chief Engineer, Drainage</b>	
	Repair and Renovation to Berhampur Drainage Division Office Building	5.00
	Imp. to Section Office at Jagatsinghpur of Cuttack Drainage Division	2.50
	Imp to Drainage Sub-Division No.-IV Erasama of Cuttack Drainage Division.	2.50
	Imp. to Sub-Division Office Building at Puri of Bhubaneswar Drainage Division	2.50
	Improvement to Non-Residential Building of MCII Division & Sub-Division at Manijanga.	5.00
	Imp. to Drainage Division Office Building at Bhadrak	5.00
	Improvement of office building of SE & EE at Balasore	5.00
	Imp. to Inespection bungalow at Naraj & Guest house at Brajabeharipur	5.00
	<b>Total (Drainage)</b>	<b>32.50</b>
	<b>CCE,Anandapur Barrage</b>	
	<b>Salandi Canal Division</b>	
	Sanitary fitting and water supply & electrification of Sub-Division Office building at Khaira	3.00
	Improvement of Rest Shed at Khaira	3.00
	Improvement to Section office at Ria Markona	3.00
	Improvement to Salandi Nivas, Bhadrak	5.00
	Improvement to Divison Office Building at Bhadrak	5.00
	<b>Sub-Total</b>	<b>19.00</b>
	<b>Baitarani Division</b>	
	Improvement to section office building at Keshdurapal	1.00
	Improvement to rest shed at Remal .	1.00
	Improvement to sub-divisional office building at Bidyadharpur	3.00
	Improvement of office building of Baitarani Flood Sub-Divn, at Salapada	4.00
	Improvement of Rest shed at Salapada	4.00
	<b>Sub-Total</b>	<b>13.00</b>
	<b>Total CCE,Anandapur Barrage</b>	<b>32.00</b>
	<b>CE&amp;BM,Upper Mahanadi Basin</b>	
	<b>Bolangir Irrigation Division</b>	

Sl. No.	Name of Work	Provision during 2010-11
<b>1</b>	<b>2</b>	<b>4</b>
	Office Building	5.00
	<b>Sub-Total</b>	<b>5.00</b>
	<b>Hariharjoe Irrigation Colony, Biramaharajpur</b>	
	Office Building	3.00
	<b>Sub-Total</b>	<b>3.00</b>
	<b>Sonepur Irrigation Colony, Sonepur</b>	
	Sub-Division Office Building	5.00
	<b>Sub-Total</b>	<b>5.00</b>
	<b>Upper Suktel Irrigation Colony at Khaprakhol</b>	
	Sub-Division Office Building	3.00
	<b>Sub-Total</b>	<b>3.00</b>
	<b>Main Dam Division, Burla</b>	
	Renovation and repair to office building of the Superintending Engineer, Hiraakud Dam Circle, Burla	10.00
	Improvement to DFC Guest House at Burla	5.00
	<b>Sub-Total</b>	<b>15.00</b>
	<b>Canal Division, Bargarh</b>	
	Sub-Division Office at Bargarh	5.00
	Improv to Sub-Division Office at Barpali	3.00
	<b>Sub-Total</b>	<b>8.00</b>
	<b>Sundargarh Irrigation Division</b>	
	Imp to Division Office Building	8.00
	Imp to Ib at Sundargarh	5.00
	<b>Sub-Total</b>	<b>13.00</b>

**Total (CE&BM,UMB) 52.00**

**G.Total 450.00**